

Brother LC - 57



Refill Volume

20 – 30 ml Black approx.
20 ml Colour approx.

Re-fill Instructions

1. Turn the cartridge upside down and locate the clear window at the centre.

2. Drill a hole in the centre of the ridge. (See figure)
Approximate drill size is 1/16" or 1.59mm

Note: Pack tissues on both sides of the ridge to prevent excess ink from leaking into the outer case of the cartridge.

3. Draw up ink into the syringe and slowly inject it into the cartridge. When the cartridge is full, bubbles of ink will appear around the needle.

4. Use a tissue to clean around the re-fill hole. Neatly daub hot glue over the hole and seal with a wet finger.

Note: Do not let excess glue run down the sides of the ridge as this may interfere with the ink sensor.

5. Rest the cartridge right side up to check that the seal does not leak.



Troubleshooting

Always contact PCS if further assistance is required.

Checklist

Black/Colour ink
20ml Syringe with needle
Gloves

Clean Up

Skin: Scrub with Solvol soap or bleach.

Clothing: Try soaking in Napi-San or similar – however it is best to avoid soiling clothes with this ink!

Bench Top: Methylated spirits will remove ink from laminate or similar surfaces.

